

U.S. DEPARTMENT OF HEALTH AND HUMAN SERVICES / PUBLIC HEALTH SERVICE
CENTERS FOR DISEASE CONTROL AND PREVENTION / NATIONAL CENTER FOR ENVIRONMENTAL HEALTH

Vessel Name	Inspection Date	Port	Results Presented To	Score
DISNEY WONDER	9/6/01	Port Canaveral	CAPTAIN	99
Cruise Line	No. Pax	No. Crew	Inspection Type	Inspected By
Disney	2665	969	Periodic Inspection	Mike Hanika Jaret Ames

SUMMARY OF INSPECTION VIOLATIONS

Item No.	Description	Points
* Miscellaneous		0
10	Swimming pools / spas maintained, safety equipment	0
18	Cross-contamination storage, preparation, transportation	0
19	Food protected storage, preparation, display, service, transportation; Original containers, labeling; Food handling minimized; In-use food dispensing, preparation utensils stored	0
21	Nonfood-contact surfaces designed, constructed, maintained, installed, located	0
26	Food-contact surfaces equipment / utensils clean; Safe	0
29	Facilities convenient, accessible, designed, installed	0
33	Decks / bulkheads / deckheads construction, repair, clean	1
40	IPM procedures developed; followed; outer openings protected	0
41	Child Activity Centers facilities, diaper changing, operation	0

DETAILS OF INSPECTION VIOLATIONS

NO.	LOCATION	REF.	POINTS	CRITICAL	DESCRIPTION
1	BEACH BLANKET BUFFET	19	0	No	DRIED PRUNES, APRICOTS, BANANAS, COCONUT, RAISINS, SHAVED ALMONDS, AND WALNUTS IN BOWLS ALONG THE DISPLAY LINE WERE NOT FULLY PROTECTED BY THE SNEEZE SHIELD. <i>These have been repositioned for service behind the sneeze guards. Sealed items such as jellies and peanut butter, will be placed to the front.</i>
2	BEACH BLANKET BUFFET	18	0	Yes	BOWLS OF DRIED PRUNES, APRICOTS, BANANA, COCONUT, RAISINS, SHAVED ALMONDS, AND WALNUTS ON THE PASSENGER SELF-SERVICE DISPLAY WERE BEING COVERED AND RETURNED TO THE GALLEY REFRIGERATION UNITS TO BE SERVED AGAIN. <i>Smaller portions will be displayed for service, and any leftover amounts will be discarded after service.</i>
3	BEACH BLANKET GALLEY	33	1	No	DECKS ALONG THE GUTTERWAYS AND SCUPPERS WERE IN DISREPAIR AND DIFFICULT TO CLEAN. <i>The repair work is scheduled to be carried out in dry-dock (9-23 September 2001).</i>
4	POTABLE WATER - SPA'S	10	0	No	THE HEALTH RISK SIGNS AT THE SPAS DID NOT WARN AGAINST USE BY PARTICULARLY SUSCEPTIBLE PEOPLE, SUCH AS THOSE WHO ARE IMMUNOCOMPROMISED. <i>A new sign is on order by DCL Shoreside.</i>
5	POTABLE WATER - SPAS/MICKEY'S EAR POOL	10	0	No	THE DRAIN COVERS WERE NOT ANTI-VORTEX. <i>We will contact your office to discuss this subject.</i>
6	INTEGRATED PEST MANAGEMENT (IPM)	40	0	No	THE WRITTEN IPM PLAN WAS NOT AVAILABLE FOR REVIEW. THERE WERE NO DOCUMENTS CONFIRMING TRAINING OF CREW MEMBERS OR CONTRACTORS WHO APPLY PESTICIDES. THERE WAS NO ESTABLISHED PIER-SIDE INSPECTION OF INCOMING SHIPMENTS OF FOOD AND SUPPLIES FOR PESTS. <i>The New IPM Plan is being drafted at DCL Shoreside offices, and will be distributed to the ship in the near future. Rentokill will provide copies of certificates for restricted use applicators. We will train and appoint one member of the Hotel Stores team to examine and spot check provisions entering the vessel that might harbor pests.</i>
7	OCEANAIRE'S CLUB	41	0	No	THERE WAS NO SIGN POSTED IN THE CHILDREN'S TOILET ADVISING THE PROVIDERS TO WASH THEIR HANDS AND THE CHILDREN'S HANDS AFTER ASSISTING CHILDREN USE THE TOILET. <i>DCL Shoreside office will contact CDC requesting a variance for this item.</i>
8	SIGNALS BAR	29	0	Yes	THE HAND WASH STATION FOR THE FRONT BAR REQUIRES PASSAGE THROUGH A CLOSED DOOR TO THE PANTRY. <i>This will be installed by ELX during dry-dock (9-23 September 2001).</i>
9	POTABLE WATER	*	0	No	THE MANAGEMENT, OPERATION, AND RECORD KEEPING IN THE POTABLE WATER SYSTEM, POOLS, AND SPAS WAS EXCEPTIONAL. SOME AREAS EXCEEDED THE STANDARDS SET IN THE VSP OPERATIONS MANUAL. <i>We appreciate this feedback.</i>
10	FOOD SERVICE-GENERAL	26	0	Yes	THE CHOPPER BLADES WERE NOT BEING DISASSEMBLED AND CLEANED AFTER EACH USE. <i>Dismantling and cleaning of this item will be added to the Daily Sanitation Checklist of the Chef de Cuisine in each area.</i>
11	DINING ROOMS	21	0	No	THE VENEER ON SOME OF THE WAITER STANDS WAS CHIPPED. <i>This will be repaired during dry-dock (9-23 September 2001).</i>

12 **AFT DINING ROOM-DECK 3**

33

1

No

THE WOODEN DECKING WAS IN POOR REPAIR.

This flooring will be replaced with a tile floor in dry-dock (9-23 September 2001).

13 **FOOD SERVICE-GENERAL**

33

1

No

THE POURED DECK COVERING IN VARIOUS AREAS SUCH AS THE HOT GALLEYS, DISH WASHING, AND THE POT WASHES WAS IN POOR REPAIR.

This flooring will be repaired in dry-dock (9-23 September 2001).

14 **FOOD SERVICE-GENERAL**

*

0

No

OVERALL FOOD TEMPERATURES AND OPERATIONS NOTED IN THE GALLEYS AND PROVISIONS WERE OUTSTANDING DURING TODAY'S INSPECTION.

We appreciate this feedback.